

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
www.nclabor.com/elevator.htm  
919-807-2770

Report Number <b>12214-48-2751</b> State Number <b>11519</b>
-----------------------------------------------------------------------

EQUIPMENT INSPECTED

State Number: <b>11519</b>	Type of Unit: Passenger	Floor to Floor: 1 to 6
Capacity: 4000	Manuf: SOUTHERN	Speed: 100
Landings: 6	Installed: 09/04/1986	Rope Size: 5/8
Volts: 480	Complied: 10/16/1986	Entrances: 1
OWNER	OCCUPANT	
ELIZABETHTOWN LUMBERTON POWER	ELIZABETHTOWN LUMBERTON POWER	
PO BOX 1899	3100 W BROAD ST	
ELIZABETHTOWN, NC, 28337	ELIZABETHTOWN, NC, 28337	

INSPECTION INFORMATION

Inspection Date 08/01/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BLADEN	9
-------------------------------	----------------------------	---------------------------------	--------------------------	------------------	---

VIOLATIONS

n/a No violations found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: RANDY COATS Inspector \_\_\_\_\_

THIS IS NOT AN INVOICE	To make changes to the invoice mailing address please call: 919-733-0372
	An invoice will be mailed to: ELIZABETHTOWN LUMBERTON POWER PO BOX 1899 ELIZABETHTOWN, NC, 28337