

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 12221-7-3569 State Number 11205

3

	E	QUIPMENT INSPECTED			
State Number: 11205 Capacity: 2500 Landings: 3 Volts: 220 OWNER THE GREYSTONE INN 2663 ROARING GAP DR. ROARING GAP, NC, 28668	Manuf: THYSSEN Installed: 07/25/19	Type of Unit: Passenger Manuf: THYSSEN KRUPP Installed: 07/25/1985 Complied: 07/25/1985 OCCUPANT THE GREYSTONI 2663 ROARING G ROARING GAP, N		GAP DR.	
	INS	PECTION INFORMATION			
Inspection Date 08/08/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 7 - Hoffman	County ALLEGHANY	
		VIOLATIONS			
8.6 PROVIDE OPERA	ATION OF THE 1ST AND 3RD F	LOOK POSITION INDICATO	JK LIGHTS		
Items must be corrected by: 09/	07/2012				
Notify the Elevator Bureau in writing complainace with current codes.	g on Corrected Violations Form w	when the following corrections	have been made in order to b	oring your equipment into	
Violations pointed out to: GREYSTONE INN 336-363-2211			Inspector		
T	o make changes to the invoice mai	iling address please call: 919-7	33-0372		

THE GREYSTONE INN

2663 ROARING GAP DR. ROARING GAP, NC, 28668