



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
12236-36-3763
State Number
837

EQUIPMENT INSPECTED

State Number: 837	Type of Unit: Freight	Floor to Floor: B to -
Capacity: 3000	Manuf: MONARCH	Speed: 75
Landings: 2	Installed: 02/27/1948	Rope Size: 5/8
Volts: 575	Complied: 10/16/1958	Entrances: 2
OWNER	OCCUPANT	
JOHN ELDER	JOHN ELDER	
674 GILMER ST	674 GILMER ST	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 08/23/2012	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------------	----------------------------------	---------------------------	--------------------

1

VIOLATIONS

left elevator notifaiction and tried to contact owner

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: n/a

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

JOHN ELDER
674 GILMER ST
BURLINGTON, NC, 27215