

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927

Report Number 12242-36-079 State Number 25483

1

	E	QUIPMENT INSPECTED			
State Number: 25483	Type of Unit: Pa	senger Floor to Floor: 1 to 3		to 3	
Capacity: 2500	Manuf: SCHINDLER Installed: 02/07/2008 Complied: 02/07/2008		Speed: 100	Speed: 100 Rope Size: 0 Entrances: 1	
Landings: 3			Rope Size: 0		
Volts: 208			Entrances: 1		
OWNER	OCCUPANT				
ETHAN POINTE APARTMENTS	ETHAN POINTE APARTMENTS				
2978 ETHAN POINTE DRIVE	1176 KIRKPATRICK ROAD				
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215			
	INS	PECTION INFORMATION			
Inspection Date 08/29/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
Notify the Elevator Bureau in writing omplainace with current codes.	g on Corrected Violations Form w	hen the following corrections	have been made in order to bri	ng your equipment into	
Violations pointed out to: KAREN V	/EZINA 336-584-3337		Inspector		
То					
THIS IS NOT AN INVOICE An invoice will be mailed to: ETHAN POINTE APARTMENTS 2978 ETHAN POINTE DRIVE					

2978 ETHAN POINTE DRIVE BURLINGTON, NC, 27215

An invoice will be mailed to: