

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 12242-36-3358 State Number 26097

1

	E	EQUIPMENT INSPECTED			
State Number: 26097 Type of Unit: Pa		ssenger Floor to Floor: 1 to 3		to 3	
Capacity: 2500	Manuf: SCHINDLER		Speed: 100		
Landings: 3	Installed: 05/13	Installed: 05/13/2008		Rope Size:	
Volts: 208	Complied: 05/13/2008		Entrances: 1		
OWNER	OCCUPANT				
ETHAN POINTE APARTMENT	S	ETHAN POINTE APARTMENTS			
2978 ETHAN POINTE DRIVE		1176 KIRKPATRICK RD			
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215			
	INS	SPECTION INFORMATION			
Inspection Date 08/29/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
otify the Elevator Bureau in writin	ng on Corrected Violations Form v	when the following corrections	have been made in order to bri	ing your equipment into	
iolations pointed out to: KAREN	VEZINA 336-584-3337		Inspector		
т	o make changes to the invoice ma	iling address please call: 919-7	33-0372		
THIS IS NOT AN	ETHAN POINTE APARTMENTS				
INVOICE A	an invoice will be mailed to:				

BURLINGTON, NC, 27215