



INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**12254-48-5149**  
State Number  
**23850**

EQUIPMENT INSPECTED

State Number: <b>23850</b>	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 3000	Manuf: OTIS	Speed: 150
Landings: 3	Installed: 06/02/2006	Rope Size: 0
Volts: 208	Complied:	Entrances: 1
OWNER		OCCUPANT
COMMUNITY ASSOCIATION MANAGEMENT		COLONY II BLDG 6
PO BOX 8126		908 RESORT CIRLCE
OCEAN ISLE BEACH, NC, 28469		SUNSET BEACH, NC, 28467

INSPECTION INFORMATION

Inspection Date 09/10/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

VIOLATIONS

8.6.4.7.4	Remove the water from the pit floor.
8.6.4.8.1	Clean the machine room (machinery space) of all debris.
2.27.1.1.2	Put the in car emergency telephone in proper working order.

Items must be corrected by: 09/30/2012

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: UNAVAILABLE

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

COMMUNITY ASSOCIATION MANAGEMENT  
PO BOX 8126  
OCEAN ISLE BEACH, NC, 28469