NCDOL NCDOL NA Department of John

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 12262-48-1276 State Number H1086

EQUIPMENT INSPECTED						
State Number: H1086 Ty		Type of Unit: H	Type of Unit: Hand Lift		Floor to Floor: 1 to 2	
Capacity: 750 Man		Manuf: ACCEL	Manuf: ACCEL		Speed: 20	
Landings: 2 Ins		Installed: 09/19	/2000	Rope Size:		
Volts: 120 Com		Complied: 09/1	9/2000	Entrances: 2		
OWNER			OCCUPANT			
LOCKWOOD FOLLY COUNTRY CLUB		CLUB	LOCKWOOD FOLLY COUNTRY CLUB			
18 CLUBHOUSE DR, SW			18 CLUBHOUSE DR, SW			
SUPPLY, NC, 28462			SUPPLY, NC, 28462			
		INSP	PECTION INFORMATION			
Inspection Date 09/18/2012		Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
			VIOLATIONS			
3.6.4.7.1	Clean the elev	ator pit.				
2.14.7.1.3	Put the in car emergency light in working order.					
	Put the in car emergency telephone in proper working order.					

Items must be corrected by: 10/08/2012

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: Jeff Inspector _____

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

LOCKWOOD FOLLY COUNTRY CLUB

An invoice will be mailed to: 18 CLUBHOUSE DR, SW SUPPLY, NC, 28462