



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**12324-48-1046**  
State Number  
**23201**

### EQUIPMENT INSPECTED

State Number: <b>23201</b>	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: OTIS	Speed: 100
Landings: 2	Installed: 11/17/2005	Rope Size:
Volts: 208	Complied: 11/17/2005	Entrances: 1

#### OWNER

CROSS CREEK LAND COMPANY  
5019 CAROLINA BEACH RD.  
WILMINGTON, NC, 28412

#### OCCUPANT

CROSS CREEK COMMONS  
1105 NEW POINTE BLVD  
LELAND, NC, 28451

### INSPECTION INFORMATION

Inspection Date 11/19/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

### VIOLATIONS

8.6.4.7.1	Clean the elevator pit.
2.27.1.1.2	Put the in car emergency telephone in proper working order.

Items must be corrected by: 12/09/2012

Elevator Name: # 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: STORE MGMT.

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CROSS CREEK LAND COMPANY  
5019 CAROLINA BEACH RD.  
WILMINGTON, NC, 28412