

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 12325-36-1058 State Number 16832

1

	E	QUIPMENT INSPECTED			
State Number: 16832	Type of Unit: Passenger		Floor to Floor:	Floor to Floor: 1 to 3	
Capacity: 2500	Manuf: THYSSEN KRUPP		Speed: 135	Speed: 135	
Landings: 3	Installed: 11/13/1997		Rope Size:	Rope Size:	
Volts: 200	Complied: 11/13/1997		Entrances: 1		
OWNER		OCCUPANT			
TWINS LAKE CENTER	TWINS LAKE CENTER				
100 WADE COBLE DR		100 WADE COBLE DR			
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215			
	INS	SPECTION INFORMATION			
Inspection Date 11/20/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
none found					
	ting on Corrected Violations Form v	when the following corrections ha	ave been made in order to bri	ing your equipment into	
omplainace with current codes.  Violations pointed out to: sue 336	5 524 0467		Imamaatan		
_	o-524-946 <i>1</i>				
	To make changes to the invoice ma	ice mailing address please call: 919-733-0372			
THIS IS NOT AN INVOICE	An invoice will be mailed to:	TWINS LAKE CENTER 100 WADE COBLE DR BURLINGTON, NC, 2721	15		