

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 12332-36-2269 State Number 14232

1

	E	QUIPMENT INSPECTED			
State Number: 14232	Type of Unit: Passenger		Floor to Floor:	Floor to Floor: B to 3	
Capacity: 4000	Manuf: THYSSEN KRUPP		Speed: 125	Speed: 125	
Landings: 4	Installed: 08/22/1991		Rope Size:	Rope Size:	
Volts: 460	Complied: 08/22/1991		Entrances: 1		
OWNER		OCCUPANT			
KOURY PROPERTIES CENTER		KOURY MANANGMENT			
PO BOX 850		3060 S CHURCH ST			
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215			
	INS	SPECTION INFORMATION			
Inspection Date 11/27/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
none found					
Notify the Elevator Bureau in writing omplainace with current codes.	g on Corrected Violations Form v	when the following corrections	have been made in order to br	ing your equipment into	
violations pointed out to: Steve Jen	try 336-585-1559				
	o make changes to the invoice ma				
THIS IS NOT AN INVOICE A	n invoice will be mailed to:	KOURY PROPERTIES PO BOX 850 BURLINGTON, NC, 27			