

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-807-2770

Report Number 12345-48-5731 State Number H1353

EQUIPMENT INSPECTED

State Number: H1353	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: GARAVENTA	Speed: 12
Landings: 2	Installed: 02/27/2003	Rope Size: 0
Volts: 120	Complied: 02/27/2003	Entrances: 2
OWNER	OCCUPANT	
VICTORIA RAG PATCH	VICTORIA RAG PATCH	
10164 BEACH DRIVE SW	10164 BEACH DRIVE SW	
CALABASH, NC, 28468	CALABASH, NC, 28468	

INSPECTION INFORMATION

Inspection Date 12/10/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	10
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------	----

VIOLATIONS

N/A REPAIR UNIT TO RUN DOWN.
8.6.4.13.1[a] Properly maintain hoistway door interlocks or mechanical locks and electric contacts. Top and bottom locks hanging up.

Items must be corrected by: 12/30/2012

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Randy

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

VICTORIA RAG PATCH
10164 BEACH DRIVE SW
CALABASH, NC, 28468