



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**12362-54-3334**  
State Number  
**23091**

EQUIPMENT INSPECTED

State Number: <b>23091</b>	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 4500	Manuf: OTIS	Speed: 125
Landings: 2	Installed: 10/14/2005	Rope Size:
Volts: 480	Complied: 03/20/2006	Entrances: 1
OWNER	OCCUPANT	
NC DEPARTMENT OF CORRECTIONS	BERTIE CORRECTIONAL / BLU-WING	
218 COOPER HILL RD	218 COOPER HILL RD	
WINDSOR, NC, 27983	WINDSOR, NC, 27983	

INSPECTION INFORMATION

Inspection Date 12/27/2012	Type Inspection Routine	Certificate Status Re-issued	Inspector 54 - Green	County BERTIE
-------------------------------	----------------------------	---------------------------------	-------------------------	------------------

8

VIOLATIONS

8.6.4.7.4	Remove the oil from the pit floor. REPAIR LEAKING VIC FITTING.
8.6.4.7.1	Clean the elevator pit.

Items must be corrected by: 01/26/2013

Elevator Name: BLUE

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: CHARLES GURGANUS

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

NC DEPARTMENT OF CORRECTIONS  
218 COOPER HILL RD  
WINDSOR, NC, 27983