## NCDOL NCDOL NA Department of John

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 13004-36-3421 State Number 24931

1

		EQUIPMENT INSPECTED			
State Number: 24931	mber: 24931 Type of Unit: Passenger		Floor to Floor: 1 to 3		
Capacity: 2100	Manuf: THYSSEN KRUPP		Speed: 80	Speed: 80	
Landings: 3	Installed: 07/17/2007		Rope Size: 0		
Volts: 208	Complied: 07/1	7/2007	Entrances: 1		
OWNER		OCCUPANT			
ELON UNIVERSITY		COLONNADES- MOF	FITT HALL (B)		
		336 DALTON MCMIC			
ELON UNIVERSITY, NC, 27244 ELON, NC, 27244					
	П	NSPECTION INFORMATION			
Inspection Date 01/04/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
NONE FOUND					
Elevator Name: MOFFIT HA	II (B)				
	ting on Corrected Violations Form	when the following corrections	have been made in order to bri	ng vour equipment into	
omplainace with current codes.		e			
/iolations pointed out to: Bob W	illis 336.278.2000		Inspector		
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN	ELON UNIVERSITY  An invoice will be mailed to:  ELON UNIVERSITY, NC. 27244				
INVOICE					
INVOICE					