



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
13010-54-1391
State Number
8633

EQUIPMENT INSPECTED

State Number: 8633	Type of Unit: Freight	Floor to Floor: 1 to 3
Capacity: 10000	Manuf: SOUTHERN	Speed: 60
Landings: 3	Installed: 07/08/1976	Rope Size:
Volts: 560	Complied: 07/08/1976	Entrances: 2
OWNER	OCCUPANT	
AVOCA INC	AVOCA INC	
PO BOX 129	841 AVOCA FARM ROAD	
MERRY HILL, NC, 27957	MERRY HILL, NC, 27957	

INSPECTION INFORMATION

Inspection Date 01/10/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 54 - Green	County BERTIE
-------------------------------	----------------------------	---------------------------------	-------------------------	------------------

8

VIOLATIONS

2.14.7.1.4 Put the car top light in working order.

Items must be corrected by: 02/09/2013

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: TOM RAY

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

AVOCA INC
PO BOX 129
MERRY HILL, NC, 27957