

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 13029-7-2737 State Number H1334

2

	EG	QUIPMENT INSPECTED			
State Number: H1334	Type of Unit: 1	Hand Lift	Floor to Floor:	1 to 2	
Capacity: 750	Manuf: GARA	VENTA	Speed: 11		
Landings: 2	Installed: 01/24	1/2003	Rope Size: 0		
Volts: 220	Complied: 01/2	24/2003	Entrances: 2		
OWNER		OCCUPANT			
ANTIOCH BAPTIST CHURCH		ANTIOCH BAPTIST CHURCH			
580 ANTIOCH CHURCH ROAI	D	580 ANTIOCH C	580 ANTIOCH CHURCH ROAD		
TAYLORSVILLE, NC, 28681		TAYLORSVILLI	TAYLORSVILLE, NC, 28681		
	INS	PECTION INFORMATION			
Inspection Date 01/29/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 7 - Hoffman	County ALEXANDER	
		VIOLATIONS			
NONE					
otify the Elevator Bureau in writi omplainace with current codes.	ng on Corrected Violations Form w	then the following corrections	have been made in order to b	oring your equipment into	
iolations pointed out to: ANTIO	CH BAPTIST CH. 828-632-2929				
1	Γο make changes to the invoice mai				
THIS IS NOT AN INVOICE	ANTIOCH BAPTIST CHURCH sn invoice will be mailed to: 580 ANTIOCH CHURCH ROAD TAYLORSVILLE, NC, 28681				