



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
13044-36-2064
State Number
H1241

EQUIPMENT INSPECTED

State Number: H1241	Type of Unit: Hand Lift	Floor to Floor: 1 to 3
Capacity: 750	Manuf: GARAVENTA	Speed: 10
Landings: 3	Installed: 04/24/2002	Rope Size:
Volts: 18	Complied:	Entrances: 2
OWNER	OCCUPANT	
GROVE PARK BAPTIST CHURCH	GROVE PARK BAPTIST CHURCH	
108 TRAIL ONE	108 TRAIL ONE	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 02/13/2013	Type Inspection Routine	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	----------------------------------	---------------------------	--------------------

1

VIOLATIONS

2.1.2.5	Adjust all hoistway doors to work properly to allow proper operation
2.1	Take steps to secure bottom floor door handle

Items must be corrected by: 03/15/2013

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: SUE ETHRIDGE 336-227-2910

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

GROVE PARK BAPTIST CHURCH
108 TRAIL ONE
BURLINGTON, NC, 27215