

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 13050-36-4410 State Number 24721

1

	E	QUIPMENT INSPECTED			
State Number: 24721	Type of Unit: Pa	assenger	Floor to Floor: 1	to 4	
Capacity: 5000	Manuf: TKE		Speed: 350		
Landings: 4	Installed: 06/25	2008 Rope Size: 3/4			
Volts: 480	Complied:		Entrances: 1		
OWNER		OCCUPANT			
LABCORP	LABCORP HEADQUARTERS				
531 S SPRING STREET	531 S SPRING STREET				
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215			
·		·			
	INS	PECTION INFORMATION			
Inspection Date 02/19/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
none found					
omplainace with current codes. Tiolations pointed out to: LORI			Inspector		
	T 1 1				
THIS IS NOT AN	To make changes to the invoice mailing address please call: 919-733-0372				
INVOICE	An invoice will be mailed to:	LABCORP 531 S SPRING STREET BURLINGTON, NC, 272	215		