

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 13056-36-4582 State Number 16089

		EQUIPMENT INSPECTED			
State Number: 16089 Capacity: 2100 Landings: 3 Volts: 208 OWNER Type of Unit: Passenger Manuf: THYSSEN KRU Installed: 11/16/1995 Complied: 11/27/1995		senger	Floor to Floor: B Speed: 100	to 1F	
		995	Rope Size:		
		1995	Entrances: 2		
			OCCUPANT		
ALAMANCE-BURLINGTON	N SCHOOL SYSTEM		EASTLAWN SCHOOL		
1712 VAUGHN RD			502 N GRAHAM HOPEDA	ALE	
BURLINGTON, NC, 27215			BURLINGTON, NC, 27217		
	I.	NSPECTION INFORMATIO	N		
Inspection Date 02/25/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
installed to be readily 8.6 Take steps to replace	g with the applicable code requirem y visible and securelattached to the e falling and loose sheet rock at top re sign at each landing	controller	and the name of the person or fire	n performing the test, shall be	
Items must be corrected by: Notify the Elevator Bureau in w. complainace with current codes. Violations pointed out to: terry	riting on Corrected Violations Form	when the following correction			
			Inspector		
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	ALAMANCE-BURLINGTON SCHOOL SYSTEM An invoice will be mailed to: 1712 VAUGHN RD BURLINGTON, NC, 27215				