



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
13056-36-5264
State Number
25045

EQUIPMENT INSPECTED

State Number: 25045	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2000	Manuf: TOCE	Speed: 100
Landings: 2	Installed: 11/14/2007	Rope Size:
Volts: 200	Complied:	Entrances: 2

OWNER

THE CITY OF BURLINGTON
425 SOUTH LEXINGTON STREET
BURLINGTON, NC, 27215

OCCUPANT

THE OLD FIRST UNION BUILDING
244 W DAVIS STREET
BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 02/25/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

- 5.1.21.1 Put the in car alarm bell in working order when 110 removed will not work.
- 2.27.1.1.2 Put the in car emergency telephone in proper working order.
- 8.6.4.13.1[] Properly maintain door restrictors, where required.
- 8.6 provide screw for certificate frame
- 8.6.1.7.2 A metal tag with the applicable code requirement(s) and date(s) performed, and the name of the person or firm performing the test, shall be installed to be readily visible and securely attached to the controller

Items must be corrected by: 03/27/2013

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: john 336-256-0937

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

THE CITY OF BURLINGTON
425 SOUTH LEXINGTON STREET
BURLINGTON, NC, 27215