## NCDOL NCDOL NA Department of later

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 13063-48-5784 State Number 23583

		EQUIPMENT INSPECTED		
State Number: 23583	Number: 23583 Type of Unit: Passeng		Floor to Floor: 1 to 4	
Capacity: 3000	Manuf: THYSSI		Speed: 125	
Landings: 4	Installed: 01/10/2006		Rope Size:	
Volts: 208	Complied: 01/10/2006		Entrances: 1	
OWNER	OCCUPANT			
CAM	ISLANDER RESORT - BLDG. #33			
P.O. BOX 8126	157 VIA OLD SOUND BLVD			
OCEAN ISLE BEACH, NC, 284				
		SPECTION INFORMATION		
Inspection Date 03/04/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
		VIOLATIONS		
Items must be corrected by: 03. Notify the Elevator Bureau in writicomplainace with current codes.	ng on Corrected Violations Form	when the following corrections		
Violations pointed out to: UNAVA	.ILABLE 		Inspector	
	To make changes to the invoice mailing address please call: 919-733-0372			
THIS IS NOT AN INVOICE	an invoice will be mailed to:	CAM P.O. BOX 8126 OCEAN ISLE BEACH,	NC, 28469	