



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**13080-36-3949**  
State Number  
**4698**

EQUIPMENT INSPECTED

State Number: <b>4698</b>	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 7500	Manuf: SOUTHERN	Speed: 60
Landings: 2	Installed: 10/01/1962	Rope Size: 0
Volts: 550	Complied: 04/08/2004	Entrances: 1
OWNER	OCCUPANT	
CAROLINA FINISHING OF NC	CAROLINA FINISHING OF NC LLC	
PO BOX 2226	220 ELMIRA ST	
BURLINGTON, NC, 27216	BURLINGTON, NC, 27217	

INSPECTION INFORMATION

Inspection Date 03/21/2013	Type Inspection Alteration	Certificate Status Issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	-------------------------------	------------------------------	---------------------------	--------------------

1

VIOLATIONS

This unit is in compliance this date 3-21-2013

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: phillip B

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CAROLINA FINISHING OF NC  
PO BOX 2226  
BURLINGTON, NC, 27216