



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
13092-16-2792
State Number
N7.5

EQUIPMENT INSPECTED

State Number: N7.5	Type of Unit: Freight	Floor to Floor: 1 to 4
Capacity: 2000	Manuf: OTIS	Speed: 100
Landings: 4	Installed: 06/05/1975	Rope Size: 1/2
Volts: 220	Complied: 06/05/1975	Entrances: 2

OWNER

MR BLACKSTONE
C/O PAMLICO PROPERTIES
WASHINGTON, NC, 27889

OCCUPANT

THE RICH COMPANY
147 W MAIN ST
WASHINGTON, NC, 27889

INSPECTION INFORMATION

Inspection Date 04/02/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 16 - Moore	County BEAUFORT
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

7

VIOLATIONS

- 8.11.2.3 Perform a 5 year load and safety test according to the applicable codes, and provide a metal tag upon completion in its proper place or location.
2.3.3.1 Repair counterweight guard on 2nd and third floors

Items must be corrected by: 05/02/2013

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Shannon Waters / Manager

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

MR BLACKSTONE
C/O PAMLICO PROPERTIES
WASHINGTON, NC, 27889