



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
13094-36-1975
State Number
23251

EQUIPMENT INSPECTED

State Number: 23251	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: OTIS	Speed: 100
Landings: 2	Installed: 06/20/2005	Rope Size:
Volts: 480	Complied: 06/20/2005	Entrances: 1
OWNER	OCCUPANT	
KIDDE	KIDDE	
1061 CORPORATE DR	1061 CORPORATE DR	
MEBANE, NC, 27617	MEBANE, NC, 27617	

INSPECTION INFORMATION

Inspection Date 04/04/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

- 2.27.1.1.2 Put the in car emergency telephone in proper working order. (Phone does not answer automatically]
- 2.14.7.1.3 Put the in car emergency light in working order.
- 8.6.4.13.2 Where a power-operated horizontally sliding door is closed by momentary pressure or by automatic means, the closing kinetic energy and closing force shall be maintained to proper levels.
- 8.6.1.7.2 . A metal tag with the applicable code requirement(s) and date(s) performed, and the name of the person or firm performing the test, shall be installed to be readily visible and securely attached .

Items must be corrected by: 05/04/2013

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: KATHY 919-563-3888

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

KIDDE
1061 CORPORATE DR
MEBANE, NC, 27617