

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number **13099-36-2448** State Number **27993**

1

	E0	QUIPMENT INSPECTED		
State Number: 27993 Capacity: 3500 Landings: 2	ty: 3500 Manuf: OTIS gs: 2 Installed: 08/29/2011		Floor to Floor: 1 to 2 Speed: 100 Rope Size: Entrances: 1	
Volts: 208				
	complica.	OCCUDANT	Entrances. 1	
OWNER LAB CORP	OCCUPANT LAB CORP			
1447 YORK COURT		1447 YORK COURT		
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215		
	INS	PECTION INFORMATION		
Inspection Date 04/09/2013	Type Inspection Compliance	Certificate Status Prev Issued	Inspector 36 - Kirkman	County ALAMANCE
		VIOLATIONS		
complainace with current codes	vriting on Corrected Violations Form w s. VID STUBBLEFIELD 336-516-1117	then the following corrections ha	we been made in order to bri	
	To make changes to the invoice mailing address please call: 919-733-0372			
THIS IS NOT AN INVOICE	An invoice will be mailed to:	LAB CORP 1447 YORK COURT		

BURLINGTON, NC, 27215