NCDOL NCDOL

THIS IS NOT AN INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 13120-48-405 State Number 22838

EQUIPMENT INSPECTED						
State Number: 22838		Type of Unit	Passenger	Floor to Floor: 1 to 3		
1 2		Manuf: OTI	fanuf: OTIS			
Landings: 3 Installed: 03/0		•				
Volts: 240 Complied: 03/02			3/02/2005	2/2005 Entrances: 1		
OWNER			OCCU	OCCUPANT		
COMMUNITY ASSOCIATION MGMT.			VILL	AS ON OSPREY RIDGE		
P.O. BOX 8126			186 C	186 CLUBHOUSE RD.		
OCEAN ISLE, NC, 28469			SUNSET BEACH, NC, 28468			
		I	NSPECTION INFORMATION			
		Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK 10	
			VIOLATIONS			
2.15.2	Replace the cracked, worn, or missing car guides.					
2.27.3.1	Put the Phase I i	Put the Phase I fire service feature in proper working order. No light at recall switch				
2.27.3.3	Put the Phase II fire service feature in proper working order. 10 Days to repair					
8.6.4.7.1	Clean the elevator pit.					
n/a	Clean under car					
Items mu	st be corrected by: (05/10/2013				
Notify the Ele		iting on Corrected Violations Form	n when the following corrections	have been made in order to	bring your equipment into	
Violations pointed out to: Unavailable Inspector						
po						

P.O. BOX 8126

OCEAN ISLE, NC, 28469

COMMUNITY ASSOCIATION MGMT.

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to: