



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
13126-36-0184
State Number
4164

EQUIPMENT INSPECTED

State Number: 4164	Type of Unit: Freight	Floor to Floor: 1 to 3
Capacity: 6000	Manuf: MONARCH	Speed: 60
Landings: 3	Installed: 03/18/1959	Rope Size:
Volts: 550	Complied: 05/21/1959	Entrances: 2
OWNER	OCCUPANT	
CAROLINA FINISHING OF NC LLC	CAROLINA FINISHING OF NC LLC	
PO BOX 2226	220 ELMIRA ST	
BURLINGTON, NC, 27216	BURLINGTON, NC, 27217	

INSPECTION INFORMATION

Inspection Date 05/06/2013	Type Inspection Condemned	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	------------------------------	----------------------------------	---------------------------	--------------------

1

VIOLATIONS

TAKE STEPS TO PROPERLY LAND ELEVATOR. THIS UNIT HAS BEEN DORMANT FOR MORE THAN 12 MONTHS

1. Remove power wires from MDP to elevator controller. 2. Barricade or lock all all landings to prevent accidental entry. 3. Elevator must be placed on bottom floor.

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Rhonda Perry 336-227-2770

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CAROLINA FINISHING OF NC LLC
PO BOX 2226
BURLINGTON, NC, 27216