



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
13128-36-3094
State Number
H225

EQUIPMENT INSPECTED

State Number: H225	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 500	Manuf: PORCHLIFT	Speed: 10
Landings: 2	Installed: 06/16/1987	Rope Size:
Volts: 110	Complied: 06/16/1987	Entrances: 2

OWNER

NORTHSIDE CHURCH OF CHRIST
PASTOR ROBERT BREWINGTON
BURLINGTON, NC, 27216

OCCUPANT

NORTHSIDE CHURCH OF CHRIST
820 HARRIS STREET
BURLINGTON, NC, 27216

INSPECTION INFORMATION

Inspection Date 05/08/2013	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------------	----------------------------------	---------------------------	--------------------

1

VIOLATIONS

Left elevator notification

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: N/A

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

NORTHSIDE CHURCH OF CHRIST
PASTOR ROBERT BREWINGTON
BURLINGTON, NC, 27216