

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-807-2770

Report Number 13128-36-4623 State Number N1.10

EQUIPMENT INSPECTED

State Number: N1.10	Type of Unit: Freight	Floor to Floor: B to 1
Capacity: 1500	Manuf: PARK	Speed: 50
Landings: 2	Installed: 11/12/1976	Rope Size: 5/8
Volts: 208	Complied: 11/12/1976	Entrances: 1

OWNER

JOHN BURTON-CHAD PORTAFIELD
PO BOX 2083
BURLINGTON, NC, 27215

OCCUPANT

MAIN STREET FLEE MARKET
612 S MAIN ST
BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 05/08/2013	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------------	----------------------------------	---------------------------	--------------------

1

VIOLATIONS

none found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: N/A

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

JOHN BURTON-CHAD PORTAFIELD
PO BOX 2083
BURLINGTON, NC, 27215