



INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
13154-48-5497
State Number
H2475

EQUIPMENT INSPECTED

State Number: H2475	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: GARAVENTA	Speed: 17
Landings: 2	Installed: 06/03/2013	Rope Size:
Volts: 120	Complied: 06/03/2013	Entrances: 1
OWNER	OCCUPANT	
THE VILLAGE AT FORT CASWELL	THE VILLAGE AT FORT CASWELL	
100 CASWELL BEACH ROAD	100 CASWELL BEACH ROAD	
OAK ISLAND, NC, 28465	OAK ISLAND, NC, 28465	

INSPECTION INFORMATION

Inspection Date 06/03/2013	Type Inspection New	Certificate Status Issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	------------------------	------------------------------	--------------------------	---------------------

10

VIOLATIONS

n/a No violations found

Elevator Name: # 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Daniel

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

THE VILLAGE AT FORT CASWELL
100 CASWELL BEACH ROAD
OAK ISLAND, NC, 28465