

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 13175-36-0911 State Number 4872

1

	E	QUIPMENT INSPECTED			
State Number: 4872	Type of Unit: Freigl	nt	Floor to Floor: 1 to 2		
Capacity: 1500	Manuf: THYSSEN KRUPP Installed: 05/10/1963		Speed: 40	Speed: 40 Rope Size:	
Landings: 2			Rope Size:		
Volts: 480	Complied: 06/19/19	63	Entrances: 1		
OWNER		OCC	CUPANT		
CAROLINA ACTIVITIES INC		W E WHITE EST			
202 N FIFTH ST		202 N FIFTH ST			
MEBANE, NC, 27203		MEBANE, NC, 27203			
	INS	SPECTION INFORMATION			
Inspection Date 06/24/2013	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
Notify the Elevator Bureau in writ omplainace with current codes.	ing on Corrected Violations Form v	when the following corrections l	nave been made in order to bri	ng your equipment into	
violations pointed out to: tom 336	5-228-2475		Inspector		
	To make changes to the invoice ma				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	CAROLINA ACTIVITIE 202 N FIFTH ST MEBANE, NC, 27203	ES INC		