

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-807-2770

Report Number 13175-36-2887 State Number 2153
--

EQUIPMENT INSPECTED

State Number: 2153	Type of Unit: Freight	Floor to Floor: 1 to 3
Capacity: 4000	Manuf: MONARCH	Speed: 60
Landings: 3	Installed: 07/22/1953	Rope Size:
Volts: 550	Complied: 07/22/1953	Entrances: 2
OWNER INTERNATIONAL TEXTILE GROUP, INC. 906 ANTHONY ST BURLINGTON, NC, 27215		OCCUPANT BURLINGTON FINISHING 906 ANTHONY ST BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 06/24/2013	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------------	----------------------------------	---------------------------	--------------------

1

VIOLATIONS

left message to set up inspection

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: tom 336-228-2475

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

INTERNATIONAL TEXTILE GROUP, INC.
906 ANTHONY ST
BURLINGTON, NC, 27215