



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
13175-36-4011
State Number
H42

EQUIPMENT INSPECTED

State Number: H42	Type of Unit: Hand Lift	Floor to Floor: UL to LL
Capacity: 300	Manuf: WECO	Speed: 25
Landings: 2	Installed: 12/11/1980	Rope Size:
Volts: 110	Complied: 12/11/1980	Entrances: 1

OWNER
EBENEZER UNITED CHURCH
734 APPLE ST
BURLINGTON, NC, 27215

OCCUPANT
EBENEZER UNITED CHURCH
734 APPLE ST
BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 06/24/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

none found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: BRANDON DAWSON 336-226-6227

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

EBENEZER UNITED CHURCH
734 APPLE ST
BURLINGTON, NC, 27215