

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 13183-48-3528 State Number 20869

		EQUIPMENT INSPECTED			
State Number: 20869	Type of Unit:	Passenger	Floor to Floor	: 1 to 4	
Capacity: 2500	Manuf: OTIS	3	Speed: 100	Speed: 100	
Landings: 4	Installed: 02/	Installed: 02/04/2003		Rope Size: 0	
Volts: 208	Complied: 02/04/2003		Entrances: 1		
OWNER	OCCUPANT				
1769 HORBORAGE CONDO		1769 HORBORA	GE CONDO		
1769 HORBORAGE DR.					
OCEAN ISLE, NC, 28469					
	I	NSPECTION INFORMATION			
Inspection Date 07/02/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
		VIOLATIONS			
Items must be corrected by: 0	7/22/2013				
Notify the Elevator Bureau in wri complainace with current codes.	ting on Corrected Violations Form	n when the following corrections	have been made in order to	bring your equipment into	
Violations pointed out to: Unava			• —		
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	1769 HORBORAGE CO 1769 HORBORAGE DR OCEAN ISLE, NC, 2846	₹.		