



INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
13205-8-4466
State Number
H2233

EQUIPMENT INSPECTED

State Number: H2233	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: SAVARIA	Speed: 14
Landings: 2	Installed: 08/23/2010	Rope Size:
Volts: 110	Complied:	Entrances: 1
OWNER	OCCUPANT	
ANSON ANSON CO BOARD OF EDUCATION	WADESBORO ELEMENTARY SCHOOL	
320 CAMDEN ROAD	321 CAMDEN ROAD	
WADESBORO, NC, 28170	WADESBORO, NC, 28170	

INSPECTION INFORMATION

Inspection Date 07/24/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 8 - Burris	County ANSON	4
-------------------------------	----------------------------	---------------------------------	-------------------------	-----------------	---

VIOLATIONS

NONE

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: MALVIN DAVIS 704-695-2725

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ANSON ANSON CO BOARD OF EDUCATION
320 CAMDEN ROAD
WADESBORO, NC, 28170