N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
13211-8-4768
State Number
H2265

EQUIPMENT INSPECTED

State Number: **H2265**
Capacity: 750
Landings: 2
Volts: 115

Type of Unit: Hand Lift
Manuf: NATL W-O-V
Installed: 02/08/2011
Complied: 02/08/2011

Floor to Floor: 1 to 2
Speed: 9
Rope Size:
Entrances: 2

OWNER
ANSON COUNTY ARTS COUNCIL
P.O. BOX 332
WADESBORO, NC, 28170

OCCUPANT
ANSONIA THEATRE
112 S RUTHERFORD STREET
WADESBORO, NC, 28170

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County
07/30/2013	Routine	Re-issued	8 - Burris	ANSON

4

VIOLATIONS

NONE

Elevator Name: STAGE LIFT

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: CATHERINE CRANDELL 704-694-4950 Inspector _____

THIS IS NOT AN INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:
ANSON COUNTY ARTS COUNCIL
P.O. BOX 332
WADESBORO, NC, 28170