



INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
13212-16-5465
State Number
13414

EQUIPMENT INSPECTED

State Number: 13414	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2000	Manuf: ESCO	Speed: 120
Landings: 2	Installed: 08/24/1989	Rope Size: 0
Volts: 480	Complied: 03/23/2005	Entrances: 1
OWNER	OCCUPANT	
NORTHSIDE HIGH SCHOOL	NORTHSIDE HIGH SCHOOL	
7868 FREE UNION CHURCH ROAD	7868 FREE UNION CHURCH ROAD	
PINETOWN, NC, 27865	PINETOWN, NC, 27865	

INSPECTION INFORMATION

Inspection Date 07/31/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 16 - Moore	County BEAUFORT
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

7

VIOLATIONS

- 8.6.4.15 Take steps to place the car emergency light in proper working order.
- 8.6.5.6 Flexible hose and fittings assemblies installed between the check valve or control valve and the cylinder, and which are not equipped with an overspeed valve shall be replaced not more than 6 years beyond the installation date.
- 2.27.1.1.2 Put the in car emergency telephone in proper working order.

Items must be corrected by: 08/30/2013

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Wanda Wilkerson

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

NORTHSIDE HIGH SCHOOL
7868 FREE UNION CHURCH ROAD
PINETOWN, NC, 27865