NEDOL N. Dopument of Labor

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 13267-48-3029 State Number H1086

	EQ	QUIPMENT INSPECTED			
State Number: H1086 Capacity: 750 Landings: 2 Volts: 120 OWNER LOCKWOOD FOLLY COUNTRY CLUB 18 CLUBHOUSE DR, SW SUPPLY, NC, 28462			Floor to Floor Speed: 20 Rope Size:	_	
		9/2000	Entrances: 2		
		OCCUPANT LOCKWOOD FOLLY COUNTRY CLUB 18 CLUBHOUSE DR, SW SUPPLY, NC, 28462			
	INSI	PECTION INFORMATION			
Inspection Date 09/24/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
		VIOLATIONS			
Items must be corrected by: Notify the Elevator Bureau in w	: 10/24/2013 riting on Corrected Violations Form wl	hen the following corrections	have been made in order to	bring your equipment into	
complainace with current codes.	•	and the following corrections			
Violations pointed out to: Janette		Inspector			
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	LOCKWOOD FOLLY O 18 CLUBHOUSE DR, S SUPPLY, NC, 28462			