



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
13295-8-3773
State Number
20826

EQUIPMENT INSPECTED

State Number: 20826	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: SOUTHERN	Speed: 90
Landings: 2	Installed: 08/09/2002	Rope Size: 0
Volts: 208	Complied: 08/09/2002	Entrances: 1
OWNER	OCCUPANT	
CAROLINA FARMERS M. INSURANCE	CAROLINA FARMERS BLDG	
515A W SALISBURY ST	515A W SALISBURY ST	
ASHEBORO, NC, 27203	ASHEBORO, NC, 27203	

INSPECTION INFORMATION

Inspection Date 10/22/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 8 - Burris	County RANDOLPH
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

76

VIOLATIONS

8.6.4.15 RESTORE ELEVATOR EMERGENCY LIGHTS & ALARM

Items must be corrected by: 11/21/2013

Elevator Name: VISITOR ELEVATOR

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: MABLE HARE

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CAROLINA FARMERS M. INSURANCE
515A W SALISBURY ST
ASHEBORO, NC, 27203