

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 13296-52-079 State Number 966

		EQUIPMENT INSPECTED			
State Number: 966	Type of Unit: Passenger		Floor to Floor: B to 4		
Capacity: 2000 Manuf: OTIS Landings: 5 Installed: 02/20/1		Speed: 100			
				2	
Volts: 220	Complied: 09/17/2	003	Entrances: 1		
OWNER		OCCUPANT	OCCUPANT		
35 PATTON CONDO ASSOC	CIATION	35 PATTON CONDO ASSOCIATION			
P.O.BOX 1021		35 PATTON AVE			
ASHEVILLE, NC, 28802		ASHEVILLE, NC, 28801			
	IN	ISPECTION INFORMATION			
Inspection Date 10/23/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 52 - Sosebee	County BUNCOMBE	11
					11.
8.11.2.2.2 Perform an annua	al no load safety test and provide pro	VIOLATIONS  per tags. Last date 7-12. 5 yea	ur full load test is due 10-31	-13	
8.11.2.2.2 Perform an annua	ıl no load safety test and provide pro		ur full load test is due 10-31	-13	
Items must be corrected by:	11/22/2013 riting on Corrected Violations Form	per tags. Last date 7-12. 5 yea	vator Name: ELEVATOR #	<i>‡</i> 1	

P.O.BOX 1021

ASHEVILLE, NC, 28802

35 PATTON CONDO ASSOCIATION