



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
13296-8-2448
State Number
6454

EQUIPMENT INSPECTED

State Number: 6454	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 5000	Manuf: SOUTHERN	Speed: 75
Landings: 2	Installed: 09/25/1969	Rope Size:
Volts: 240	Complied: 10/01/1969	Entrances: 2
OWNER	OCCUPANT	
ELASTIC THERAPY INC	ELASTIC THERAPY INC	
PO BOX 4068	718 INDUSTRIAL PARK AVE	
ASHEBORO, NC, 27204-4068	ASHEBORO, NC, 27204	

INSPECTION INFORMATION

Inspection Date 10/23/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 8 - Burris	County RANDOLPH
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

76

VIOLATIONS

NONE

Elevator Name: FREIGHT ELEVATOR

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: HAROLD ALBRIGHT

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ELASTIC THERAPY INC
PO BOX 4068
ASHEBORO, NC, 27204-4068