## NCDOL N.C. Department of Labor

THIS IS NOT AN INVOICE

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 13297-48-5459 State Number 23791

		EQUIPMENT INSPECTED		
State Number: 23791	3791 Type of Unit: Special		Floor to Floor: 1 to 5	
Capacity: 2500		CHINDLER	Speed: 125	
Landings: 5	Installed: (	04/26/2006	Rope Size: 0	
Volts: 208	Complied:		Entrances: 1	
OWNER		OCCUPANT		
CAMS	THE PRESERVE BUILDING #2 - CAR#2			
1630 MILITARY CUTOFF RD				
WILMINGTON, NC, 28403		OAK ISLAND, NC, 28465		
	1	INSPECTION INFORMATION		
Inspection Date 10/24/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
		VIOLATIONS		
8.6.4.7.4 8.11.2.2.2 n/a	Remove the oil from the pit flo Perform the annual no load saft LOOSE HAND RAILS			
Items must be corrected by: 1	11/23/2013			
Notify the Elevator Bureau in wri complainace with current codes.	iting on Corrected Violations For	m when the following corrections	have been made in order to	bring your equipment into
Violations pointed out to: Calvin			Inspector	

1630 MILITARY CUTOFF RD.

WILMINGTON, NC, 28403

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to: