



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**13302-8-3332**  
State Number  
**6280**

### EQUIPMENT INSPECTED

State Number: <b>6280</b>	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 6000	Manuf: SOUTHERN	Speed: 75
Landings: 2	Installed: 01/09/1969	Rope Size:
Volts: 550	Complied: 12/29/1997	Entrances: 1
OWNER	OCCUPANT	
SAPONA MFG COMPANY	SAPONA MANUFACTURING CO	
PO BOX 128	2478 CEDAR FALLS RD	
CEDAR FALLS, NC, 27230	CEDAR FALLS, NC, 27230	

### INSPECTION INFORMATION

Inspection Date 10/29/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 8 - Burris	County RANDOLPH
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

76

### VIOLATIONS

8.6.4.13 REPLACE DAMAGED HOISTWAY DOOR ASTRAGAL ON BOTH DOORS 1ST & 2ST FLOOR  
8.6.1.7.2 HANG ANNUAL TEST TAG ON MACHINE ROOM CONTROLERS ON ALL ELEVATORS.

Items must be corrected by: 11/28/2013

Elevator Name: MIDDLE ELEVATOR #3

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: BUD NANCE 336.625.2727

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

SAPONA MFG COMPANY  
PO BOX 128  
CEDAR FALLS, NC, 27230