

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 13329-48-3165 State Number 20788

	EQUI	PMENT INSPECTED		
State Number: 20788	Type of Unit: Passer	nger	Floor to Floor: 1 to 2	
Capacity: 2100	Manuf: SCHINDLE	R	Speed: 100	
Landings: 2	Installed: 04/22/2003	2	Rope Size:	
Volts: 208	Complied: 04/24/20	02	Entrances: 2	
OWNER		OCCUPANT		
ELIZABETHTOWN BAPTIST CHURCH		ELIZABETHTOWN B	APTIST CHURCH	
1800 W BROAD ST		1800 W BROAD ST		
ELIZABETHTOWN, NC, 28337		ELIZABETHTOWN, N	NC, 28337	
	INSPEC	TION INFORMATION		
Inspection Date 11/25/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BLADEN
		VIOLATIONS		
Items must be corrected by: 12/25/Notify the Elevator Bureau in writing of		the following corrections have b	peen made in order to bring yo	our equipment into
complainace with current codes.		Č		
Violations pointed out to: Linda Clark			Inspector	
	To make changes to the invoice mailing address please call: 919-733-0372			
THIS IS NOT AN INVOICE An i	nvoice will be mailed to:	ELIZABETHTOWN BAPTIS' 1800 W BROAD ST ELIZABETHTOWN, NC. 283		