



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
13329-48-5093
State Number
15342

EQUIPMENT INSPECTED

State Number: 15342	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: OTIS	Speed: 100
Landings: 2	Installed: 03/09/1994	Rope Size:
Volts: 208	Complied: 03/15/1994	Entrances: 1
OWNER	OCCUPANT	
PRESBYTERY OF COASTAL CAROLINA	PRESBYTERY OF COASTAL CAROLINA	
807 WEST KING ST	807 WEST KING ST	
ELIZABETHTOWN, NC, 28337	ELIZABETHTOWN, NC, 28337	

INSPECTION INFORMATION

Inspection Date 11/25/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BLADEN
-------------------------------	----------------------------	---------------------------------	--------------------------	------------------

9

VIOLATIONS

2.14.7.1.4	Put the car top light in working order.
8.11.2.2.2	Perform the annual no load safety test

Items must be corrected by: 12/25/2013

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: De Scott

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

PRESBYTERY OF COASTAL CAROLINA
807 WEST KING ST
ELIZABETHTOWN, NC, 28337