

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 13344-48-1993 State Number H1522

		EQUIPMENT INSPECTED			
State Number: H1522 Type of Unit: Hand Li		and Lift	Floor to Flo	or: 1 to 2	
Capacity: 750	Manuf: THYSS	EN KRUPP	Speed: 12		
Landings: 2	Installed: 09/01/	Installed: 09/01/2004			
Volts: 115	Complied: 09/01/2004		Rope Size: Entrances:	2	
OWNER		OCCUPANT			
COUNTY OF BRUNSWICK	COUNTY OF BRUNSWICK BRUNSWICK COUNTY LIBRARY				
PO BOX 249		1040 CALABASH RD.			
BOLIVIA, NC, 28422	CALABASH, NC, 28467				
	IN	ISPECTION INFORMATION			
Inspection Date 12/10/2013	Type Inspection Routine	Certificate Status Not Issued	Inspector 48 - Martin	County BRUNSWICK	
		VIOLATIONS			
complainace with current codes.	ting on Corrected Violations Form	when the following corrections l			
Violations pointed out to: CHRIS	STIE 				
THIS IS NOT AN INVOICE	To make changes to the invoice m	To make changes to the invoice mailing address please call: 919-733-0372			
	An invoice will be mailed to:	COUNTY OF BRUNSW PO BOX 249 BOLIVIA, NC, 28422	/ICK		