

Violations pointed out to: Bob 336.278.2000

THIS IS NOT AN

INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 13361-36-176 State Number 24229

1

EQUIPMENT INSPECTED				
State Number: 24229	Type of Unit: Passenger		Floor to Floor: 1 to 3	
Capacity: 2000	Manuf: OTIS		Speed: 125	
Landings: 3	Installed: 11/03/2006		Rope Size: 0	
Volts: 208	Complied: 11/03/2006		Entrances: 1	
OWNER		OCCUPANT		
ELON UNIVERSITY	OAKS BUILDING(C)			
803 HAGGARD AVENUE	1006 ELON ACORN DRIVE			
ELON, NC, 27244	ELON, NC, 27244			
]	INSPECTION INFORMATION		
Inspection Date 12/27/2013	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
		VIOLATIONS		
Elevator Name: BUILDING 1/4				
otify the Elevator Bureau in writing	g on Corrected Violations For	m when the following corrections l	have been made in order to bri	ng your equipment into

Page 1 of 1

ELON UNIVERSITY

ELON, NC, 27244

803 HAGGARD AVENUE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

Inspector ___