

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 14017-36-2171 State Number 4196

	F	EQUIPMENT INSPECTED			
State Number: 4196	Type of Unit: Freight		Floor to Floor: 1 to	Floor to Floor: 1 to 2	
Capacity: 6000		Manuf: ROTARY			
Landings: 2	Installed: 04/28/1959		Rope Size:	Speed: 60 Rope Size:	
Volts: 440	Complied: 04/28/1959		Entrances: 1		
OWNER		OCCUPANT			
AMI	AMI				
2609 TUCKER ST		204 N GRA-HOPEDALE RD			
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215			
	IN	SPECTION INFORMATION			
Inspection Date 01/17/2014	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
	NER -Donnie Neuenberger 301-44				
Notify the Elevator Bureau in write complainace with current codes.	ting on Corrected Violations Form v	when the following corrections	have been made in order to bri	ng your equipment into	
iolations pointed out to: Donnie					
	To make changes to the invoice ma	ailing address please call: 919-7			
THIS IS NOT AN		AMI			
INVOICE	An invoice will be mailed to:	2609 TUCKER ST BURLINGTON, NC, 272	215		