



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**14021-36-2427**  
State Number  
**12179**

EQUIPMENT INSPECTED

State Number: <b>12179</b>	Type of Unit: Dumbwaiter	Floor to Floor: B to 3
Capacity: 200	Manuf: ATLAS	Speed: 50
Landings: 4	Installed: 12/30/1986	Rope Size: 1/4
Volts: 240	Complied: 12/30/1986	Entrances: 1

OWNER

BURLINGTON INSURANCE GROUP  
238 INTERNATIONAL  
BURLINGTON, NC, 27215

OCCUPANT

BURLINGTON INSURANCE GROUP  
238 INTERNATIONAL  
BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 01/21/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

none found

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: jack336-229-9090

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BURLINGTON INSURANCE GROUP  
238 INTERNATIONAL  
BURLINGTON, NC, 27215