



INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
14022-48-5267
State Number
26744

EQUIPMENT INSPECTED

State Number: 26744	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: OTIS	Speed: 100
Landings: 2	Installed: 10/27/2009	Rope Size:
Volts: 208	Complied:	Entrances: 1
OWNER	OCCUPANT	
BEN LYONS	DOLPHIN SHORE CLUBHOUSE	
P.O. BOX 87	2284 DOLPHIN SHORES DRIVE	
REISTERSTOWN, MD, 21136	SUPPLY, NC, 28462	

INSPECTION INFORMATION

Inspection Date 01/22/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

VIOLATIONS

2.2.5.1 Put the pit lights in proper working order.

Items must be corrected by: 02/21/2014

Elevator Name: # 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: BRIAN ASHLINE

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BEN LYONS
P.O. BOX 87
REISTERSTOWN, MD, 21136