



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
14027-36-5938
State Number
28048

EQUIPMENT INSPECTED

State Number: 28048	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 2500	Manuf: SCHINDLER	Speed: 125
Landings: 3	Installed: 08/01/2011	Rope Size:
Volts: 208	Complied: 08/01/2011	Entrances: 1
OWNER	OCCUPANT	
EDG PROPERTIES LLC	ELON TOWN CENTER	
PO BOX 2676	130 N WILLIAMSON AVENUE	
GREENSBORO, NC, 27402	ELON, NC, 27244	

INSPECTION INFORMATION

Inspection Date 01/27/2014	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	---------------------------	--------------------

1

VIOLATIONS

NONE FOUND

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: (336) 538-9668 office

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

EDG PROPERTIES LLC
PO BOX 2676
GREENSBORO, NC, 27402